




CONFIGURATION UTILITY

UDOT Automated Traffic Signal Performance Measures

Jamie Mackey, P.E, PTOE
UDOT Statewide Signal Engineer
jamiemackey@utah.gov




ATSPM Configuration






ATSPM Configuration - Signal






ATSPM Configuration – Approach






ATSPM Configuration – Detection





ATSPM Configuration – Detection





ATSPM Configuration – Configuration Table

Configuration Table

Detector ID	Det. Channel	Phase	Perm. Phase	Overlap	Direction	Enabled	Detection Types	Movement Type	Lane Number	Lane Type	МРН	Dist. From StopBar	Decision Point	Move. Delay	Min Speed Filter	Comment
722014	14	2		False	NB	Truo	Advanced Count Advanced Speed	Thru	1	Vehicle	40	350		15	5	was 6 dt 4-5 13
722016	16	6		False	SB	True	Advanced Count Advanced Speed	Thru	1	Vehicle	40	350		15	5	was 8 dt 4-5 13
722017	17	5		False	NB	True	Stopbar Presence	Left	1	Vehicle						
722018	18	2		False	NB	True	Stopbar Presence	Thru	1	Vehicle	40					
722019	19	2		False	NB	True	Stopbar Presence	Thru	2	Vehicle	40					
722020	20	2		False	NB	True	Stopbar Presence	Thru-Right	1	Vehicle	40					
722021	21	5		False	NB	True	Lane-by-lane Count	Left	1	Vehicle						
722022	22	2		False	NB	True	Lane-by-lane Count	Thru	1	Vehicle	40					3-27-15 - it was WB L1.
722023	23	2		False	NB	True	Lane-by-lane Count	Thru	2	Vehicle	40					3-27-15 - it was WB T1.
722024	24	2		False	NB	True	Lane-by-lane Count	Thru-Right	1	Vehicle	40					3-27-15 - it was WB R1
722027	27	1		False	SB	True	Stopbar Presence	Left	1	Vehicle						
722028	28	6		False	SB	True	Stopbar Presence	Thru	1	Vehicle	40					
722029	29	6		False	SB	True	Stopbar Presence	Thru	2	Vehicle	40					
722030	30	6		False	SB	True	Stopbar Presence	Thru-Right	1	Vehicle	40					
722031	31	1		False	SB	True	Lane-by-lane Count	Left	1	Vehicle						
722032	32	6		False	SB	True	Lane-by-lane Count	Thru	1	Vehicle	40					
722033	33	6		False	SB	True	Lane-by-lane Count	Thru	2	Vehicle	40					
722034	34	6		False	SB	True	Lane-by-lane Count	Thru	3	Vehicle	40					
722035	35	6		False	SB	True	Lane-by-lane Count	Right	1	Vehicle	40					
722038	38	4		False	EB	True	Stopbar Presence	Left	1	Vehicle						
722039	39	4		False	EB	True	Stopbar Presence	Thru	1	Vehicle						
722040	40	4		False	EB	True	Lane-by-lane Count	Left	1	Vehicle						
722041	41	4		False	EB	True	Lane-by-lane Count	Thru	1	Vehicle						
722042	42	4		False	EB	True	Lane-by-lane Count	Right	1	Vehicle						



DETECTION TYPES

UDOT Automated Traffic Signal Performance Measures


Jamie Mackey, P.E, PTOE UDOT Statewide Signal Engineer



Detect	Metric	
None	€ ← ←	Phase Termination Chart Split Monitor Preemption Details Pedestrian Delay
Lane-by-lane Presence Lane Group Presence		Purdue Split Failure
Lane-by-lane Stop Bar Count	←←	Turning Movement Counts Approach Volume
Advanced Count	€	Purdue Coordination Diagram Approach Volume
Advanced Speed	<u></u>	Approach Speed (requires detection with speed service)




Detection – Lane-by-lane Presence






Detection – Lane-by-lane Count






Detection – Lane-by-lane Count w/ Speed Restriction






Detection – Advanced Count & Speed






Wavetronix Matrix Standard Detection La

Standard Detection Layout w/ Click 650





Detection Channel Order

- 1. Presence zones, inside to outside. If P&P zones, the queue zone is first.
- 2. Count channels, inside to outside
- 3. YRA zones, inside to outside
- 4. Count zones in exit lanes, inside to outside (often skipped)

Matrix Sensor

Order

- 1. Phase 2
- 2. Phase 6
- 3. Phase 4
- 4. Phase 8



65' or 50' Presence zone, used for Split Failure



15' Presence zone w/ 3-sec delay in controller, not used for SPMs



Small zone, used for **Turning Movement Counts**



Small zone with 15 mph min speed filter, used for **Yellow & Red Actuations** (Note: Place immediately in front of stop bar and do not use in lanes that permit turns on red)



Wavetronix Matrix Configuration for

TMC & YRA

Turning Movement Counts

Z1 Z2 Z3 Z4 Z5 Z6

88888

Z7 Z8 Z9 10 11 **Channel Type** Invert

AND

OR


Counting

Min Speed

D = --s

E = --s

DI = --




Yellow & Red **Actuations**


D = --s

E = --s

DI = --



Max Speed



Max Speed

None -


Min Speed


15 mpl



Wavetronix Advance Count Setup

Ch1 is for Dilemma Zone and Queue







Wavetronix Advance Speed Setup

GDOT/UDOT Automated Traffic Signal Performance Measures

Installation Manual

Appendix A. Wavetronix SmartSensor Advance Configuration

In order to use a Wavetronix SmartSensor Advance with the ATSPM Speed Listener, it is necessary to configure the hardware to communicate with the system. There are two components of relevance to ATSPM, a Serial to Ethernet converter and the SmartSensor Device itself. UDOT has used the DIGI PortServer TS 4 serial to Ethernet converter (aka "Digi") in order to retrieve speed data from the Wavetronix SmartSensor Advance; however, other serial to Ethernet converters may work as well.

This appendix only covers configuration specifically related to ATSPM connection using Digi PortServers. For further information on SmartSensor configuration, please contact Wavetronix.

A.1. Serial to Ethernet Converter Configuration

Configure each port pushing speed data on the Digi as follows:


Set the Port Profile to either TCP or UDP Sockets (Select Change Profile to make a change). TCP sockets are preferred as they are more secure, more reliable and are native to the Wavetronix Advance and Matrix SmartSensors (as they are written around TCP internet protocols).

TCP:

- Under the TCP Server Port Security Settings, check the box Only allow network access from the following devices or networks. In the IP Address: box, type in the IP address of the server to receive the data. Under the Advanced Serial Settings Terminal Type: box, type in "vt100", enable Verbose connection status message and enable Enable RTS Toggle with 0 ms for both Pre-delay and Post-delay.
- 2. Click the Apply button.

UDP:

 Under the UDP Client enter the following settings: In the Send data to: box, type the name of the SPM server in Description, its IP address in Send To, "10088" in UDP Port, then click the Add button. Both this IP address and port must be publicly accessible.





Econolite Controllers: Count Detector Setup

Detector	ECPI Log	Phase
1		4
2	Х	0
3		8
4	Х	0
5		2
6	Х	0
7		6
8	Х	0
9		0
10		0
11		0
12		0
13		0
14		0
15		0
16		0


Detector	ECPI Log	Phase
17		5
18		2
19		2
20		2
21		2
22	Х	0
23	Х	0
24	Х	0
25	Х	0
26	Х	0
27		0
28		0
29		1
30		6
31		6
32		6

Detector	ECPI Log	Phase
33		6
34	Х	0
35	Х	0
36	Х	0
37	х	0
38	Х	0
39		0
40		0
41		7
42		4
43		4
44		4
45	Х	0
46	Х	0
47	Х	0
48	x	0

Detector	ECPI Log	Phase						
49		3						
50		8						
51		8						
52		8						
53	Х	0						
54	Х	0						
55	Х	0						
56	X	0						
57		0						
5		0						
	Enable ECPI Log for count zones on channels							
assigned to Phase 0								
61		0						
62		0						



Econolite Controllers: Data Logger Setup






METRICS

UDOT Automated Traffic Signal Performance Measures

Jamie Mackey, P.E, PTOE UDOT Statewide Signal Engineer



Metric: Phase Termination Chart






Detection Requirements: None

Complaint: Long red at 2 a.m., no other traffic

Before

Video detection not working at night






Detection Requirements: None

Complaint: Long red at 2 a.m., no other traffic

After

New detection technology installed




Force off


Detection Requirements: None

Phase 6




Metric: Split Monitor









Complaint: Long queue, short green








After




Example: I-15 Freeway Closure, September 9-12, 2014





Split Monitor for Incident Management

200 N. (Cedar City) @ 1400 W/I-15 SBSIG#8223 Phase 4 Sunday, September 07, 2014 12:00 AM - Saturday, September 13, 2014 11:59 PM



Implemented timing plans



Detection Requirements: None

Metric: Pedestrian Delay


EVENT CODES

45 - Ped Call on

21 - Ped Walk on

Tuesday, September 01, 2015 12:00 AM - Wednesday, September 02, 2015 12:00 AM - Phase 2


167-Ped Acutations(PA) 00:00-Min Delay 01:20-Max Delay 00:30-Average Delay(AD)



Phase 4
Side street


Phase 2

Coordinated phase






Metric: Purdue Split Failure






Metric: Turning Movement Counts



Metric: Turning Movement Counts
Detection Requirements: Stop Bar Counters




Yellow & Red Actuations



- Is green time too short? Would increasing the split fix the problem?
- Is coordination poor? Would more vehicles arriving on green fix this?
- ➤ Is sight distance poor? Are there trucks or other obstructions blocking signal?
- ➤ Is law enforcement needed? Time can be pinned down for law enforcement.




Metric: Purdue Coordination Diagram






Optimization Example: Progression Quality






Detection Requirements: Stop bar counts or approach counts

Metric: Approach Volume









Detection Requirements: Stop bar counts or approach counts

Metric: Approach Volume






Detection Requirements: Approach counts

Metric: Approach Delay

Approach Delay
 Approach Delay Per Vehicle

University Avenue @ East Bay BoulevardSignal 6402 Phase: 2 Northbound Tuesday, January 17, 2017 12:00 AM - Tuesday, January 17, 2017 11:59 PM

Average Delay Per Vehicle = 13 Seconds. Total Delay For Selected Period = 178416 Seconds



Simplified Approach Delay. Displays time between approach activation during the red phase and when the phase turns green.

Does NOT account for start up delay, deceleration, or queue length that exceeds the detection zone.






Metric: Arrivals on Red

--- Arrivals on Red
--- Percent Arrivals on Red
--- Total Vehicles

University Avenue @ East Bay BoulevardSignal 6402 Phase: 2 Northbound Tuesday, January 17, 2017 12:00 AM - Tuesday, January 17, 2017 11:59 PM

Total Detector Hits = 11725 Total AoR = 5170 Percent AoR for the select period = 44









Metric: Approach Speed

Posted Speed
85th Percentile Speed
Average MPH

SR-126 (1900 W) 5700 South (Roy) Signal 5088 Phase 6 Southbound Wednesday, September 30, 2015 12:00 AM - Wednesday, September 30, 2015 11:59 PM Detector Distance from Stop Bar: 350 feet; Min Speed Filter: 5 MPH; Time Filter: 15s after start of green to start of yellow Speed Accuracy: + - 5 MPH









Metric: Approach Speed

Riverdale Rd Shopko Signal 5008 Phase 2 Northbound
Thursday, January 10, 2013 6:00 AM - Thursday, January 10, 2013 11:00 PM
Detector Distance from Stop Bar: 350 feet; Min Speed Filter: 5 MPH;
Time Filter: 15s after start of green to start of yellow
Speed Accuracy: + - 5 MPH







ROUTE CONFIGURATION

UDOT Automated Traffic Signal Performance Measures

Jamie Mackey, P.E, PTOE UDOT Statewide Signal Engineer




Route Configuration for Link Pivot

R2: Foothill Blvd

Create New

Direction of travel to next signal


ApproachRouteDescription	ApproachOrder	
7371 - Foothill Drive Thunderbird Northbound Phase 2	1	Edit Details Delete
7223 - Foothill Drive 2100 South Northbound Phase 2	2	Edit Details Delete
7222 - Foothill Drive 1700 South Northbound Phase 2	3	Edit Details Delete
7221 - Foothill Drive 2300 East Northbound Phase 2	4	Edit Details Delete
7220 - Foothill Drive 1300 South Northbound Phase 2	5	Edit Details Delete
7503 - Foothill Drive 2100 East Northbound Phase 2	6	Edit Details Delete
7219 - Foothill Drive Sunnyside Northbound Phase 2	7	Edit Details Delete
7218 - Foothill Drive Wakara Way (660 S.) Northbound Phase 2	8	Edit Details Delete
7217 - Foothill Drive Mario Capecchi Dr (1950 E.) Northbound Phase 2	9	Edit Details Delete






Purdue Link Pivot

Purdue Link Pivot Analysis







Purdue Link Pivot

Adjustments

Customizable link delta

Final offsets

Link	Signal	Location	Link Delta	Edit Link Delta	Offset(+ to Offset)	Existing Offset	New Offset
1	7371	Foothill Drive Thunderbird	4	4	55	0	55
2	7223	Foothill Drive 2100 South	7	7	51	0	51
3	7222	7222 Foothill Drive 1700 South		0	44	0	44
4	7221	Foothill Drive 2300 East	0	0	44	0	44
5	7220	Foothill Drive 1300 South	40	40	44	0	44
6	7503	Foothill Drive 2100 East	59	59	4	0	4
7	7219	Foothill Drive Sunnyside	56	56	65	0	65
8	7218	Foothill Drive Wakara Way (660 S.)	9	9	9	0	9
9	7217	Foothill Drive Mario Capecchi Dr (1950 E.)	0	0	0	0	0

Recommended link delta

Change to offset (link delta propagated up corridor)

User-input existing programmed offsets




Purdue Link Pivot

Red indicates predicted **negative** change in AOG

Approach Link Comparisor

Approach Link Comparison													
Link	Approaches		Upstream AOG		Downstream AOG			Total Link AOG		Delta	AOG Chart		
	Upstream	Downstream	Existing	Predicted	Change	Existing	Predicted	Ch	Exist	ing Predicted	Change	Detta	AOGCHAIC
	7223 Southbound	7222 Northbound	5431	5632		5938	5824		113	59 11456			Siller State (chine h) hand
2	Foothill Drive 2100 South	Foothill Drive 1700 South	85%	88%		90%	88%		88	% 88%		6	PCD Options
	7220 Southbound	7503 Northbound	2281	4059	•	4976	5149		7257	7 9208		38	PCD Options
5	Foothill Drive 1300 South	Foothill Drive 2100 East	42%	76%		88%	92%		66	% 84%			
Corridor Summary		39585	44992		32610	36968		721	95 81960				
		mmary	72 %	82 %		68 %	77 %		70	% 80 %			

Green indicates predicted **positive** change in AOG





ATSPM ALERTS

UDOT Automated Traffic Signal Performance Measures

Jamie Mackey, P.E, PTOE UDOT Statewide Signal Engineer



System Health Alerts

- No SPM data: identifies signals with less than 500 records in the database between midnight and midnight the previous day
- Too many max outs: identifies phases with more than 90% max outs in at least 50 activations between 1 a.m. and 5 a.m.
- Too many force offs: identifies phases with more than 90% force offs in at least 50 activations between 1 a.m. and 5 a.m.
- Too many ped calls: identifies phases with more than 200 pedestrian activations between 1 a.m. and 5 a.m.
- Low PCD detector count: identifies phases with PCD detectors that have less than 100 vehicles counted between 5 p.m. and 6 p.m. the previous day.

SPM Alerts for 5/22/2016



-

SPMWatchdog@utah.gov

to marktaylor, me, signaldesk, shanejohnson, bryan.meenen, kbarnes, SWinters, tforbush, jay

--The following signals had too few records in the database: 4671 - 13400 South & 4500 West - Phase: 0 (Missing Records) 5701 - 500 South & 400 East (Btfl) - Phase: 0 (Missing Records) --The following signals had too many force off occurrences:

1224 - North Temple & Main Street - Phase: 3 (Force Offs 97.6%) 7252 - 500 South & Main Street - Phase: 2 (Force Offs 100%) 7252 - 500 South & Main Street - Phase: 6 (Force Offs 100%)

--The following signals had too many max out occurrences:

1123 - Wolcott St & 100 South - Phase: 2 (Max Outs 100%) 1124 - Sunnyside (850 S) & Gaurdsman Way - Phase: 2 (Max Outs 100%)

1124 - Sunnyside (850 S) & Gaurdsman Way - Phase: 6 (Max Outs 100%)

4024 - 7000 South (Fort Union) & 1300 East - Phase: 7 (Max Outs 92.6%)

4029 - 7200 South & 700 East - Phase: 1 (Max Outs 100%)

4103 - 4680 South (Murray-Holladay) & 2320 East (Holladay) - Phase: 5 (Max Outs 100%)

4118 - 6200 South & 3655 West (Dixie) - Phase: 2 (Max Outs 100%)

4511 - 4100 South & 3200 West - Phase: 4 (Max Outs 100%)

4820 - 4835 South & 2700 West - Phase: 2 (Max Outs 100%)

5063 - Lincoln & 24th - Phase: 4 (Max Outs 100%)

5063 - Lincoln & 24th - Phase: 8 (Max Outs 100%)

5080 - Washington & Adams - Phase: 5 (Max Outs 100%)

5170 - 200 N (Kaysville) & Main St. - Phase: 4 (Max Outs 100%)

5305 - Main St. & 200 North (Logan) - Phase: 7 (Max Outs 96.2%)

5900 - 900 W. (Kays Dr.) & 200 North, (Kaysville) - Phase: 4 (Max Outs 90.4%)

6035 - Pioneer Crossing & Millpond Drive - Phase: 8 (Max Outs 91.9%)

6608 - 100 West & 100 North - Phase: 8 (Max Outs 98.5%)

7107 - Redwood Road & 4700 South - Phase: 5 (Max Outs 93.2%)

-- The following signals had unusually low detector hits:

5134 - SR-193 (700 S) & I-15 NB (Clearfield) - Phase: 2 (Has Unusually Low Counts.)

7061 - Bangerter Hwy (SR-154) & 4100 South - Phase: 1 (Has Unusually Low Counts.)

7061 - Bangerter Hwy (SR-154) & 4100 South - Phase: 7 (Has Unusually Low Counts.)

7361 - Bangerter Hwy (SR-154) & 13400 South - Phase: 1 (Has Unusually Low Counts.)

-- The following signals have stuck ped detectors:

1023 - South Temple & 200 West - Phase: 2 (Stuck Ped.)

1023 - South Temple & 200 West - Phase: 4 (Stuck Ped)

1023 - South Temple & 200 West - Phase: 6 (Stuck Ped.)

1023 - South Temple & 200 West - Phase: 8 (Stuck Ped.)

4511 - 4100 South & 3200 West - Phase: 4 (Stuck Ped)

6009 - Main (Lehi) & I-15 SPUI - Phase: 6 (Stuck Ped.)

7826 - 9800 S (Little Cottonwood Rd) & Wasatch Blvd (3500 E) - Phase: 4 (Stuck Ped)



Alert Evaluation

1 No ATSPM data

Check communication to signal

Check controller clock

Check IP address in SPM configuration

Check VIOT = NO & DB State = All Saved (Econolite MM 9-3-1 SpFn*3)

Try enabling Upload Current

Create a WO to cold start the controller

Too many max outs

Check for recalls

Check for constant call on a detector channel

Consider whether a bandaid is necessary

Too many force offs

Should the signal be in coordination?

Is a non-coordinated phase maxing out?

Skip only 2-6 pairs and dummy phases

Too many ped calls

Check for recalls

Check for constant call on a detector channel

Low PCD detector count

Note: Evaluate the VOLUME on the PCD charts, not the phase data

Is count channel configured correctly in SPM Config Tool?


Is ECPI Log enabled for count channel?

Is the detector working?


Is the detector communicating to the controller?

Try resetting the sensor and VERIFY with Upload Current









Gap out

O Pedestrian activation (shown above phase line)


Max out

O Skip

Force off


Metric: Purdue Phase Termination Detection Requirements: None








4 Too many ped calls





Cycle Time (Seconds)








6 High PCD detector count

Washington 12th Signal 5030 Phase: 6 Southbound Thursday, August 04, 2016 12:00 AM - Thursday, August 04, 2016 11:59 PM

47% AoG




Volume Per Hour




6 High PCD detector count


Volume report for Washington 12th on the Northbound and Southbound approaches. 8/4/2016 12:00:00 AM - 8/4/2016 11:59:00 PM - Using Advanced Detection





Work Orders







LOG ACTION TAKEN

UDOT Automated Traffic Signal Performance Measures

Jamie Mackey, P.E, PTOE UDOT Statewide Signal Engineer




Log Action

Name	Jamie Mackey						
Date	1/17/2017 11:0	7:05 AM					
Signal	7220 - Foothill	Drive 1300 Sou	ıth ▼				
Agency	State Governn	nent	*				
Actions	☐Actuated Coord	d.□All-Red Inte	erval				
Activity	Coord On/Off	■Modeling					
	□Cycle Length	Traffic Stud	dy				
	☑ Detector Issue	☐Yellow Inte	erval				
	Offset	☐Force Off T	уре	Select multiple			
	□S equence	Split Adjus	tment				
	☐Time Of Day	Manual Co	mmand				
	Other						
MetricTypes	Purdue Phase	Termination	Approach Volum	ie			
metricrypes	✓ Split Monitor		■Approach Delay				
	☑ Pedestrian Del	ay	Arrivals On Red				
	□Preemption Details □Approach Speed						
	☐Turning Movement Counts ☐Yellow and Red Actuations						
☐Purdue Coordination Diagram☐Purdue Split Failure							
Comment	Identified brok	en detector and	d adjuste				

Create



Review Action and Metric Use





Review Metric Use

